

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 99.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-022775**Date Inspected:** 22-Mar-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Cui Zheng Hua**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dennis Combs, was present during the times noted above for the observations relative to the work being performed.

BAY 14

This QA Inspector observed the following work in progress for Bay 14.

ZPMC was using the Shielded Metal Arc Welding (SMAW) process.

ZPMC QC is identified as Wang Xiang Pin.

Welding variables recorded by QC appeared to comply with the approved Welding Procedure Specification (WPS).

Listed below are the locations that were identified by this QA inspector.

Component: Longitudinal Diaphragm

PCMK: SEG3019AA

Weld Number: 025

Welder: 067079

WPS-345-FCAW-2G-FCM-REPAIR

CWR 2755

Component: Floor Beam

PCMK: SEG3019C

Weld Number: 010

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Welder: 066236
WPS-B-T-2233-TC-U4b-FCM-1

Component: Vertical Shear Plate
PCMK: SEG3019BB
Weld Number: 133
Welder: 215553
WPS-B-P-2212-TC-U4b-FCM-1

Component: Vertical Shear Plate
PCMK: SEG3019BB
Weld Number: 089
Welder: 216086
WPS-B-P-2212-TC-U4b-FCM-1

Component: Vertical Shear Plate
PCMK: SEG3019BB
Weld Number: 155
Welder: 044779
WPS-B-P-2212-TC-U4b-FCM-1

Component: FB Stiffener
PCMK: SEG3019E-2
Weld Number: 151
Welder: 051356
WPS-345-FCAW-1G-FCM-REPAIR
CWR 2862


This Caltrans QA inspector received ZPMC non-destructive test (NDT) notification number 08601 from ZPMC for Bay 14. This QA inspector performed magnetic particle testing (MT) verification of welds after ZPMC had performed their MT inspection. The segment is identified as OBG Floor Beam. The weld designations reviewed are as follows.

FB3271-001-013, 014, 021, 022
SEG3019V-014, 022
SEG3019W-021
SEG3019L-054

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)



Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Combs,Dennis	Quality Assurance Inspector
Reviewed By:	Riley,Ken	QA Reviewer
